2016 Annual Drinking Water Quality Report Mooreville Richmond Water Association PWS#: 0410007, 0410032 & 0410039 May 2017

We're pleased to present to you this year's Annual Quality Water Report. This report is designed to inform you about the quality water and services we deliver to you every day. Our constant goal is to provide you with a safe and dependable supply of drinking water. We want you to understand the efforts we make to continually improve the water treatment process and protect our water resources. We are committed to providing you with information because informed customers are our best allies.

If you have any questions about this report or concerning your water utility, please contact David Faust at 662.844.0311. We want our valued customers to be informed about their water utility. If you want to learn more, please join us at any of our regularly scheduled meetings. They are held on the third Thursday of the month at 5:30 PM at the water department.

Our water source is from wells drawing from the Eutaw Aquifer. The source water assessment has been completed for our public water system to determine the overall susceptibility of its drinking water supply to identified potential sources of contamination. A report containing detailed information on how the susceptibility determinations were made has been furnished to our public water system and is available for viewing upon request. The wells for the Mooreville Richmond Water Association have received a moderate ranking in terms of susceptibility to contamination.

We routinely monitor for contaminants in your drinking water according to Federal and State laws. This table below lists all of the drinking water contaminants that were detected during the period of January 1st to December 31st, 2016. In cases where monitoring wasn't required in 2016, the table reflects the most recent results. As water travels over the surface of land or underground, it dissolves naturally occurring minerals and, in some cases, radioactive materials and can pick up substances or contaminants from the presence of animals or from human activity; microbial contaminants, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife; inorganic contaminants, such as salts and metals, which can be naturally occurring or result from urban storm-water runoff, industrial, or domestic wastewater discharges, oil and gas production, mining, or farming; pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm-water runoff, and residential uses; organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations and septic systems; radioactive contaminants, which can be regulations that limit the amount of certain contaminants in water provided by public water systems. All drinking water, including bottled drinking water, may be reasonably expected to contain at least small amounts of some contaminants. It's important to remember that the presence of these contaminants does not necessarily indicate that the water poses a health risk.

In this table you will find many terms and abbreviations you might not be familiar with. To help you better understand these terms we've provided the following definitions:

Action Level - the concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Maximum Contaminant Level (MCL) - The "Maximum Allowed" (MCL) is the highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

Maximum Contaminant Level Goal (MCLG) - The "Goal" (MCLG) is the level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum Residual Disinfectant Level (MRDL) – The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary to control microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG) – The level of a drinking water disinfectant below which there is no known or expected risk of health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

Parts per million (ppm) or Milligrams per liter (mg/l) - one part per million corresponds to one minute in two years or a single penny in \$10,000.

Parts per billion (ppb) or Micrograms per liter - one part per billion corresponds to one minute in 2,000 years, or a single penny in \$10,000,000.

| PWS ID #: | 041000 | / | 1 | EST RESULT | D | | | | |
|--|------------------|-------------------------|--|------------|----|------|-----|--|-------------------------------------|
| Contaminant | Violation Y/N | Date Collected | Level Range of Detects or Detected # of Samples Measure Exceeding MCL/ACL/MRDL Unit MCLG | | | MCLG | MCL | Likely Source of Contamination | |
| | | | | | | | | | |
| Microbiolo | ~ | | | | r | | | | |
| Microbiolo 1. Total Coliform Bacteria | gical Co | Intamina January | Positive | 2 | NA | 0 | ba | nce of coliform cteria in 5% of onthly samples | Naturally present in the environmen |
| 1. Total Coliform | Y | January | | 2 | NA | 0 | ba | cteria in 5% of | |

| 13. Chromium | N | 2015* | 2.2 | 1.5 – 2.2 | ppb | | 100 | 10 | Discharge from steel and pulp mills; erosion of natural deposits |
|--------------|---------|----------|------|-----------|------|---|-----|--------|---|
| 14. Copper | N | 2012/14* | .4 | 0 | ppm | | 1.3 | AL=1 | .3 Corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives |
| 16. Fluoride | N | 2015* | .153 | .114153 | ppm | 1 | 4 | | 4 Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories |
| 17. Lead | N | 2012/14* | 1 | 0 | ppb | | 0 | AL=1 | 5 Corrosion of household plumbing systems, erosion of natural deposits |
| Disinfection | on By-l | Products | l | | · | l | | | Tuckosks |
| Chlorine | N | 2016 | 1.2 | .5 – 2.1 | mg/l | 0 | MRI | DL = 4 | Water additive used to control microbes |

| Contaminant | Violation Y/N | Date Collected | Level Detected | Range of Detects of # of Samples Exceeding MCL/ACL/MRDL | or Unit Measure -ment | MCLG | MCL | Likely Source of Contamination |
|--------------|------------------|-------------------|-------------------|---|-----------------------------|------|--------|---|
| Inorganic | Contam | inants | | | | | | |
| 10. Barium | N | 2016 | .0889 | .08420889 | ppm | 2 | 2 | 2 Discharge of drilling wastes; discharge from metal refineries; erosion of natural deposits |
| 13. Chromium | N | 2016 | 2.5 | .7 – 2.5 | ppb | 100 | 100 | Discharge from steel and pulp mills; erosion of natural deposits |
| 14. Copper | N | 2013/15* | .3 | 0 | ppm | 1.3 | AL=1.3 | B Corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives |
| 16. Fluoride | N | 2016 | .11 | No Range | ppm | 4 | 4 | Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories |
| 17. Lead | N | 2013/15* | 1 | 0 | ppb | 0 | AL=15 | G Corrosion of household plumbing systems, erosion of natural deposits |
| Disinfection | on By-Pi | roducts | | | | | | |
| Chlorine | | | .2 .5 | - 1.9 m | g/l | 0 MR | | Nater additive used to control nicrobes |

| PWS ID #: 0410039 TEST RESULTS | | | | | | | | | |
|--------------------------------|------------------|-------------------|-------------------|--|--------------------------|------|--------|--|--|
| Contaminant | Violation Y/N | Date Collected | Level Detected | Range of Detects or # of Samples Exceeding MCL/ACL/MRDL | Unit Measure -ment | MCLG | MCL | Likely Source of Contamination | |
| Inorganic (| Contami | inants | | | | | | | |
| 10. Barium | N | 2016 | .083 | No Range | ppm | 2 | 2 | Discharge of drilling wastes; discharge from metal refineries; erosion of natural deposits | |
| 13. Chromium | N | 2016 | 2.6 | No Range | ppb | 100 | 100 | Discharge from steel and pulp mills; erosion of natural deposits | |
| 14. Copper | N | 2012/14* | .4 | 0 | ppm | 1.3 | AL=1.3 | Corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives | |
| 16. Fluoride | N | 2016 | .114 | No Range | ppm | 4 | 4 | Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer and aluminum factories | |

| 17. Lead | N | 2012/14* | 1 | 0 | ppb |) | 0 AL | =15 Corrosion of household plumbing systems, erosion of natural deposits |
|--------------|---------|----------|-----|----------|------|---|----------|--|
| Disinfection | on By-F | Products | | | | | | |
| Chlorine | N | 2016 | 1.4 | .5 – 2.3 | mg/l | 0 | MRDL = 4 | Water additive used to control microbes |

^{*} Most recent sample. No sample required for 2016.

Microbiological Contaminants:

We routinely monitor for the presence of drinking water contaminants. On system # 410007, we took 5 samples for coliform bacteria during January 2016. Two (2) of those samples showed the presence of coliform bacteria. The standard is that no more than 1 sample per month of our samples may do so. We have increased monitoring for this system for any changes in water quality. We have collected re-samples and DID NOT show any presence of Coliform Bacteria.

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Our water system is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead. The Mississippi State Department of Health Public Health Laboratory offers lead testing. Please contact 601.576.7582 if you wish to have your water tested.

All sources of drinking water are subject to potential contamination by substances that are naturally occurring or man made. These substances can be microbes, inorganic or organic chemicals and radioactive substances. All drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the Environmental Protection Agency's Safe Drinking Water Hotline at 1.800.426.4791.

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline 1.800.426.4791.

2017 will complete water line expansion on all 3 systems and new well on system 0410007.

The Mooreville Richmond Water Association works around the clock to provide top quality water to every tap. We ask that all our customers help us protect our water sources, which are the heart of our community, our way of life and our children's future.

⁽¹⁾ Total Coliform. Coliforms are bacteria that are naturally present in the environment and are used as an indicator that other, potentially-harmful, waterborne pathogens may be present or that a potential pathway exists through which contamination may enter the drinking water distribution system. We found coliform indicating the need to look for potential problems in water treatment or distribution. When this occurs, we are required to conduct assessments (s) to identify problems and to correct any problems that were found during these assessments.